

S E C R E T

25X1A

Herewith attachment #1 to [REDACTED] -18841
dated 3 March 1970

LISTING OF SLIDES

25X1A

[REDACTED] TRANSMITTER SITE

1. Road into site - Building site in background.
2. Same as #1.
3. Building site.
4. Building site - Note how efforts to compact fill causes area to mushroom out.
5. Antenna Site - Flooding caused by break in dyke.
6. Same as #4.
7. Same as #3.
8. Casting bed for prestressed concrete piles. 500' long - five piles cast at one time.
- ✓ 9. Form work - crane to remove piles from bed.
10. Showing steel in place - two piles side by side.
11. Tensioning steel by hydraulic jack.
- ✓ 12. Same as #10.
13. General view of casting bed, piles on left being cured.
14. Same as #13.
15. Same as #10.
16. Same as #11.
17. Same as #11.
18. Same as 11 - showing steel reinforcing.

S E C R E T

S E C R E T

19. Same as #11.
20. Same as #11.
21. Showing end of finished piles. Piles being cured. Piles approximately 100' long.